Incomino 80030076

PERIHELION GLOBAL, INC.

March 18, 2008
Division of Oil, Gas and Mining
1594 West North Temple
Suite 1210
Salt Lake City, Utah 84116

RECEIVED MAR 2 1 2008

DIV. OF OIL, GAS & MINING

Dear Mr. Lynn Kunzler,

This question is in reference to File No.: S/1003/0076, Mine: Perihelion Global, Inc. #1 & #2, (formerly Saturday Night 1 & 2) Operator: Perihelion Global, Inc.

What is the procedure to maintain the BLM road as shown in exhibit A (the yellow line)?

Is this to be maintained by BLM? PHGI?

Can simple back blading be conducted by a bucket loader? Does it require grader? I need to be educated.

I have included a topo map exhibit B and a detail map (exhibit C) of the patent claims owned by PHGI for your examination.

Please contact me. Thank you.

Sincerely, Symu Bearelestoner

Lynn Bartholomew

Senior Vice President

lbartholomew@perihelion.com



Exhibit A



Exhibit B




Exhibit C